Scan only last 10 symbols of the whole long code.

Steps:

Enter Setup



Keep the last symbols



Setting the last symbols



1



0



Save setting



Exit Setting

